

AEROTWIN

AM600U



L L

Audi

A3, Sportback [8P1, 8PA] 05.03 → X
Q7 [4LB] 03.06 → X

BMW

Serie X [E 70; E 71; E 84] 11.06 → X
Serie 3, Touring [E 90, E 91] 03.05 → X
Serie 3 Coupé, Cabrio [E 92, E 93] 09.06 → X
Serie 5, Touring [E 60, E 61] 07.03 → X

Citroën

C3 Picasso [A58] 02.09 → X
C4, Coupé [B5] 11.04 → X

Fiat

500 [150..] 07.07 → X
Bravo 07 [198..] 08.07 → X
Croma 05 [194..] 06.05 → X
Multipla [186..] 01.06 → X

Hyundai

i30, CW Kombi 09.07-03.10 X

Kia

Cee'd, Sport Wagon [ED/FF2] 11.06-06.09 X

Lancia

Delta [844] 07.08 → X

Land Rover Group

Freelander II 10.06 → X

Mercedes-Benz

Sprinter [NCV3] 04.06 → X

Nissan

Qashqai [J10] 12.06 → X

Renault

Twingo II [CN./GN.] 04.07 → X

Saab

9-3 [9440] 02.08 → X


Seat

Ibiza, Sportcoupé [6J1, 6J5] 02.08 → X

Skoda

Octavia, Ccmbi [1Z3, 1Z5] 05.04 → X

Volkswagen

Caddy [2K] 02.04 → X
Crafter [2E] 04.06 → X
Golf V, Variant [1K1, 1K5] 10.03 → X
Golf VI, Variant [5K1, AJ5] 10.08 → X
Jetta [1K2] 12.05 → X
Passat, Variant [3C2, 3C5] 03.05 → X
T5 [7H] 02.03-11.09 X X
Tiguan [5N1] 11.07 → X
Touran [1T1]  02.03 → X

Volvo
S60 08.04 → X
S80 I [P 23] 03.04-07.06 X
V70II 08.04-07.07 X
XC90 08.04 → X



3 397 008 585-8CT